

Mine Name: Lost Sheep Mine

Operator Name: Michael Provstgaard

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Date:

Permit Number: S0230029 Inspection Date: June 17, 2009

Reviewed:

June 18, 2009

Inspector(s): Wayne Western & Brett Gregory		Time: 11:00 am – 12:50 pm		
Other Participants: Gail Provstgaard		Mine Status ACT		
	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds	\boxtimes	\boxtimes	
2.	Public Safety (shafts, adits, trash, signs, highwalls)			
3.	Protection of Drainages / Erosion Control			
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)			
6.	Concurrent Reclamation			
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8.	Water Impoundments			
9.	Soils			
10	0. Re-vegetation			
1	1. Air Quality			

Bond Amount:

12. Other

The bond amount is \$5,400.00 and escalated until March 13, 2010.

Purpose of Inspection:

The purpose of the inspection was to determine the areas that the Permittee will use in the mining operations. The area had been part of a mine that began operations in 1948. The Division wants to clarify what areas will be part of the disturbed area.

Inspection Summary:

The Division and the Permittee did a GPS survey of the disturbed area. There are pre-law disturbed areas that outside of the disturbed area.

The Permittee proposes to construct a concrete pad in the pit and use that shaft construction.

Conclusions and Recommendations:

Inspection Date: June 17, 2009

Page 2 of 4 M/023/0029

The Division will follow up the inspection with a letter to the Permittee to provide additional information to the

adague averteur 08/10/2009

Inspector's Signature


WHW BG:

cc: (OPERATOR)

Jerry Mansfield, BLM

O:\M023-Juab\S0230029-LostSheep\inspections\ins_06-17-2009.doc

Inspection Date: June 17, 2009 Page 3 of 4 M/023/0029





Post law stockpile

Post law disturbed road cut

Inspection Date: June 17, 2009 Page 4 of 4 M/023/0029





Post law structures

Pre law abandoned truck